



17530

15162

3 Hours / 100 Marks

Seat No.

--	--	--	--	--	--	--	--

- Instructions :**
- (1) *All questions are compulsory.*
 - (2) *Illustrate your answers with neat sketches wherever necessary.*
 - (3) *Figures to the right indicate full marks.*
 - (4) *Assume suitable data, if necessary.*
 - (5) *Use of Non-programmable Electronic Pocket Calculator is permissible.*
 - (6) *Mobile Phone, Pager and any other Electronic Communication devices are not permissible in Examination Hall.*

Marks

1. A) Attempt **any three**: (4×3=12)
 - a) Define metrology. State the types.
 - b) State the Taylor's principle of gauge design.
 - c) Differentiate between 'angle gauges' and 'slip gauges'. (four points)
 - d) What is S.Q.C. ? State the benefits.

B) Attempt **any one**: (6×1=6)

 - a) Write the procedure for measuring 'Effective diameter' of screw thread, by using 'two-wire method'.
 - b) Differentiate 'line standard', 'end standard' and 'wave length standard'. (Give one application of each of them).
2. Attempt **any four**: (4×4=16)
 - a) Draw a labelled diagram showing the working mechanism of a dial indicator.
 - b) What is 'Interchangeability' ? State its need and relevance in mass-production industries.
 - c) Draw a labelled diagram of a universal bevel-protractor show its specific application on diagram.
 - d) Name the types of pitch errors. Sketch and label each type.
 - e) Distinguish between the terms "Producer's risk" and "Consumer's risk".
3. Attempt **any four**: (4×4=16)
 - a) Define the term 'comparator'. State the characteristics of a good comparator.
 - b) An angle of $117^{\circ} 8' 42''$ is to be set and measured with the help of standard angle gauges and square block. Select the minimum number of pieces and sketch the arrangement.
 - c) Differentiate between 'Variable Chart' and 'Attribute chart' (four points).
 - d) State the principles of TQM.
 - e) Explain the principle of measurement of Parkinson gear tester with a neat sketch.

P.T.O.

**Marks**4. A) Attempt **any three** :**(4×3=12)**

- a) Distinguish between 'Alignment test' and 'Performance test' of a machine tool.
- b) By using optical flat and monochromatic light source, explain how will you determine whether the given surface is convex or concave or flat.
- c) Design a general type plug gauge for checking a hole dimension $30^{+0.05}_{-0.03}$. Consider both wear allowance and gauge tolerance as 10% of work tolerance.
- d) Explain 'Cost of Quality' and 'Value of Quality' with the help of graph.

B) Attempt **any one** :**(6×1=6)**

- a) Compare single and double sampling plans.
- b) State the characteristics and applications of normal distribution curve.

5. Attempt **any two** :**(8×2=16)**

- a) With a neat sketch explain the principle of working of LVDT. State its applications.
- b) Explain the principle of measurement of a spur gear tooth thickness using a gear tooth vernier. State mathematical relations to compute chordal addendum and chordal tooth thickness.
- c) Draw a neat labelled sketch of O.C. curve. State the procedural steps of construction of O.C. curve.

6. Attempt **any two** :**(8×2=16)**

- a)
 - i) Distinguish between 'Primary texture' and 'Secondary texture'.
 - ii) Define CLA and RMS values as applied to surface roughness measurement.
- b)
 - i) State the meaning of 'Quality of Design' and 'Quality of Conformance'.
 - ii) State the importance of 'Quality audit'.
- c) Following are the inspection results of magnets for five observations. Draw appropriate control chart and conclude.

Week No.	1	2	3	4	5
No. of magnets inspected	728	724	720	730	724
Defectives found	48	83	80	58	60